Oil Field Environmental Incident Summary

Responsible Party: Bridger Transportation

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: Erickson CTB

Field Name: GLASS BLUFF Well File #: 24458

Date Incident: 2/8/2016 Time Incident: 09:00 Facility ID Number:

County: MCKENZIE Twp: 152 Rng: 103 Sec: 26 Qtr: NE NW

Location Description:

Submitted By: Michael Lee Received By:

Contact Person: Michael Lee

2009 Chenault Dr. Ste 100 Carrollton, TX 75006

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 1.5 Barrels 1.5 Barrels

Brine Other

Description of Other Released Contaminant:

none

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

N/A

Potential Environmental Impacts:

none

Action Taken or Planned:

Garner Environmental was dispatched within an hour of us receiving the call from our driver. They came in with a hydrovac and mini excavator once the OneCall was cleared. They are currently in the process of remediation by removing and disposing of affected media.

Wastes Disposal Location: At an approved facility

Agencies Involved:

Updates

Date: 2/10/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on facility site according to the report. NDIC retains oversight.